







GND

PWR

GND

OUT

MWM.ARC2LAB.COM



B27

B28

B22

B24

B23

B25

B21

B20

B43

B44

B11

B10

B11

B10

U50

C50

B30

B31

R33

R33

U30

R33

U30

B34

B32

GND

SDA

SDA

SCL

IN1

PWR

04-S014
REV 1.0